



Fig 21 - Occlusal interferences should be checked and corrected. Excess bonding agent is removed and finishing and polishing procedures are carried out as usual.



Fig 22 - Fiber-Splint Multi-Layer retained prosthesis on completion.



Fig 23 - Patient was all smiles after ultra conservative prosthesis which was metal free, economical, single sitting, durable and highly aesthetic.



Fig 24 - Intra oral radiograph upon completion.

This figure shows the use of Polydentia's Fiber-Splint application clips



REMOVAL AND REPAIR

REMOVAL: When Fiber-Splint is used in situations such as splinting traumatized teeth, it needs to be removed. Six fluted carbide burs were used under

